DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453

(707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-001782 Address: 333 Burma Road **Date Inspected:** 10-Mar-2008

City: Oakland, CA 94607

OSM Arrival Time: 1800 **Project Name:** SAS Superstructure **OSM Departure Time:** 730 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai China

CWI Name: CWI Present: Yes N/A No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A **Electrode to specification:** No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component: OBG Deck Plates**

Summary of Items Observed:

This Quality Control (QA) arrived at ZPMC for visual inspection of the Orthotropic Bridge Girders (OBG) Deck Plates that were welded by ZPMC. This QA inspectors Visual Inspection (VT) was determined to have Insufficient Fusion (IF) Over Lap (OL), Under Fill (UF), and Undercut (UC) within the weldments that were inspected. The locations and lengths of the discontinuities were recorded for tracking and distributed to the appropriate personnel for review. The deck plates inspected were numbers DP-080-001 5 ribs and DP-038-001 4 ribs.

Summary of Conversations:

No conversations today. QA inspector performed Visual Inspection of Deck Plates

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

Inspected By: Riley, Ken Quality Assurance Inspector **Reviewed By:** Hager, Craig **QA** Reviewer